SITE DATA

Year Built: 1958

Year Modernized: 2003

Student Population (2017 - 2018):

Number of Classrooms:2 (KG &1st, 2nd & 3rd)

Number of Portables: 0

PRINCIPAL PRIORITIES

- 1. Water / drinking water
- 2. Landscaping (track and irrigation)
- Lunch shelter



26960 Co Road 96, Davis | www.fairfield.djusd.net

CATEGORY:

- No Work
- [1] [2] Minor Work
- Minor Modernization
- [3] [4] Standard Modernization
- Major Modernization / Reconfiguration
- Complete Replacement

Parking

Category [0]

Additional parking spaces added to east side of existing

Concrete Paving

Category [-]

AC Paving Category [1]

 Series of long cracks to be repaired in driveway and existing parking

Ramps & Stairs Category [0]

Site Amenities Drinking Fountains Category [0]

Shade Shelter

Category [5]

Need new shade shelter

Bike Area

Category [0]

Country school-biking is not utilized at this site

Athletic Fields & Facilities Category [4]

New compacted gravel track to be constructed, hardcourts in good condition

Play Structures

Category [0]

In good condition

Landscape

Category [0]

New planter container beds by PTA

Irrigation

Category [4]

Irrigation needs to be repaired and redesigned

Fencing & Gates

Category [2]

Add service gate to north gravel parking lot for maintenance access.

CATEGORY:

- [0] No Work
- [1] Minor Work
- [2] Minor Modernization
- [3] Standard Modernization
- [4] Major Modernization / Reconfiguration
- [5] Complete Replacement

ASSESSMENT OF BUILDINGS

Exterior

Overall Rating: Category [-]

Paint

Category [-]

Door / Frames / Locks

Category [1]

Hardware to be upgraded to electronic

Windows

Category [2]

Existing single pane windows w/ new infill sliders

Roof

Category [-]

Access to roof was not acheivable

ADA Compliance

Category [1]

Truncated domes to be added to dropoff

Interior

Overall Rating: Category [2]

Interior colab space requires updating

Food Service

Category [3]

 Staff kitchen: replace cabinets and sink, keep existing refrigerator and stove. All to comply w/ ADA

Restrooms

Category [0]

Recently modernized

ASSESSMENT OF SYSTEMS

Site Utilities

Domestic Water

Category [5]

· Water quality issues reported by the district.

Fire Protection Category [0]

No applicable

Gas

Category [0]

No Applicable

Sewer

Category [0]

· No issues reported with the septic systems.

Storm Drain / Drainage

Category [0]

No issues reported.

Mechanical

Overall Rating: Category [3]

· Bard units need to be replaced.

Plumbing

Category [4]

- · Restrooms are reported to need upgrades.
- A staff restroom is needed.

Electrical Power

Category [-]

- 960 original installation, had switchgear modernization verify date of modernization.
- Main switch gear modernized, review digital as-builts for capacity. Panels are original and breakers are beginning to fail. Issues replacing parts.
- Siemens, cutler-hammer, and others (no standard manuf.)
- Voltage-120/208A-3-phase
- · One site connection from PG&E, overhead service.
- T8 lights throughout
- · No site pole lights
- · No preferred lighting and controls venders

Fire Alarm

Category [-]

- Manual pull stations
- Smoke detectors and alarms verify full coverage, likely not automatic
- No fire sprinklers verify as-builts
- Gamewell is the preferred manufacturer
- Integrated Fire System preferred vendor/consultant
- Fiber to all sites verify as-builts

Technology - Overall Site: Category [4]

- Campus Distribution for Telecommunications The campus has a conduit infrastructure which supports a Main Distribution Frame (MDF) in the Library building, along with dedicated Intermediate Distribution Frames (IDF) per building. Conduit infrastructure is ran on the canopies from building to building. No additional conduit infrastructure is needed to support low voltage infrastructure systems. Existing fiber optic backbone cabling is 62.5um along with copper backbone from MDF to each IDF room. All backbone cabling needs to be replaced.
- Recommendation: Upgrade fiber optic backbone cable to 50um (OM3) and single mode (OS2) from MDF to each IDF to obtain network speed/bandwidth and future growth

Exterior Paging System Category [0]

Exterior PA speakers are on campus

Exterior Security Cameras

Category [0]

Campus currently does not have security cameras. None are required

Exterior Wireless Access Points

Category [3]

Campus currently does not have exterior wireless access points



CATEGORY:

- No Work
- [1] Minor Work
- [2] Minor Modernization
- [3] Standard Modernization
- Major Modernization / Reconfiguration
- Complete Replacement

Building Systems

MDF

· Three floor standing data racks with ladder racking and wire managers. No Telecommunications Main Grounding Busbar (TMGB). Poor cable management. CAT5 network cabling to all workstations. Room has dedicated cooling. No master clock system. No proper grounding and bonding. Security Camera system no longer functional. No Intrusion detection system. All horizontal cabling is in surface mounted wiremold in classrooms and corridor.

Provide Telecommunication Main Grounding Busbar (TMGB) [4].

Provide dedicated cooling 24/7 [5] Upgrade fiber optic backbone cabling to multimode 50um (OM3) and single mode (OS2) [4]

Data/Voice

Category [5]

- Full VoIP CAT6A structured cabling
- Full wireless coverage

Intercom/PA/Clock

Category [0]

Carehawk System

CATV

Category [0]

Intrusion Detection

Category [5]

- Honeywell System
- · Administration, Gymnasium, Computer Lab, Library

Security Camera Category [0]

Access Control Category [5]

All doors

Audio Visual Category [4]

- Classroom room technology, Interactive boards.
- · Conference rooms, flat screen TV's
- Culinary Arts Video Streaming
- Digital Menu Boards (60" min.)

Assistive Listening System Category [4]

Lighting Category [3]

Upgraded to LED

SECTION 5





Covered Walkway



Hardcourts



Parking



Playfields / Athletics



Play Structure



Outdoor Garden



Windows



Exterior Garden Storage



Outdoor Learning

SECTION 5





Staff Work Room / Lounge



Dining Area



Water Fountains



Teaching Station / Presentation Technology



Typical Classroom



Kindergarten / Child Care Classroom



Interior Hallway



Computer Lab



SECTION 5







CDC - Child Daycare, PK - Preschool TK - Transitional Kindergarten KG - Kindergarten, INC - Inclusion

M/S - Inclusion: Moderate/Severe MI - Math Intervention, R - Reading Intervention

Electives / Labs

SCI - Science, CL - Computer Lab

Student Services

EL - English Learners, CO - Counseling INT - Intervention, OT - Occupational Therapy PSY - Psychology, SP - Speech RSP - Resource Specialist Program

Shared Spaces
LIB - Library, MPR - Multi-Purpose Room

Admin / Faculty
FW - Faculty Work, FL - Faculty Lounge,
O - Office, CF - Conference Room

Support Spaces X - Storage, T - Toilets, U - Utility, J - Janitor, K - Kitchen



■ Portable Classrooms



Main Entry



Electrical Transformer






EXISTING CAMPUS PLAN FAIRFIELD ELEMENTARY













SCOPE OF WORK CATEGORIES MA	ASTER PLAN COST (2018\$)		GRO	GROUP 1 SCOPE		GROUP 2 SCOPE	
Modernize / Reconfigure Existing Classrooms	\$	398,000	\$	-		\$	-
2. Existing Building Systems, Toilets & Improved Energy Efficiency	\$	324,000	\$	48,000		\$	-
3. Site Utilities & Infrastructure	\$	-	\$	-		\$	-
4. New Construction (Classrooms)	\$	114,000	\$	-		\$	-
5. Elementary STEM & JrHS/HS Science Programs	\$	-	\$	-		\$	-
6. JrHS/HS Electives Improvements	\$	-	\$	-		\$	-
7. Music, Drama & Performing Arts Improvements	\$	-	\$	-		\$	-
8. MPR, Student Union & Food Service Improvements	\$	305,000	\$	-		\$	305,000
9. Physical Education Improvements	\$	7,000	\$	-		\$	-
10. Staff & Community Support	\$	-	\$	-		\$	-
11. Library & Student Support Services	\$	48,000	\$	-		\$	-
12. Safety & Security	\$	285,000	\$	176,000		\$	-
13. Bike / Car Parking & Drop-Off	\$	-	\$	-		\$	-
14. Outdoor Learning Courts, Quads & Gardens	\$	-	\$	-		\$	-
15. Exterior Play Spaces, Playfields & Hardcourts	\$	203,000	\$	-		\$	-
16. Next Generation Learning Furniture	\$	67,000	\$	-		\$	67,000
17. Technology Infrastructure & Equipment	\$	87,000	\$	87,000		\$	-
Total Construction / Project Cost (2018\$) \$	1,838,000	\$	311,000		\$	372,000

The following items are excluded from this budget:

- Utility hook-up fees & City connection fees
- Off-site work and traffic signals
- Land acquisition costs
- Temporary classrooms
- Hazardous material surveys, abatement and disposal
- Escalation (costs are in 2018\$)



